



US EPA RECORDS CENTER REGION 5



ENSR International

4500 Park Glen Road

Suite 210

St. Louis Park, MN 55416-4889

(952) 924-0117

FAX (952) 924-0317

www.ensr.com

COPY

June 1, 2005

Darryl Owens
Regional Administrator
United States Environmental
Protection Agency, Region 5
Mail Code HSR-6J
77 West Jackson Boulevard
Chicago, Illinois 60604

Site Remediation Section
Director, Groundwater and Solid
Waste Division
Minnesota Pollution Control Agency
520 Lafayette Road North
St. Paul, Minnesota 55155

President
Reilly Industries, Inc.
300 North Meridian Street, Suite 1500
Indianapolis, Indiana 46204-1763

**Re: United States of America, et al. vs. Reilly Tar & Chemical Corporation, et al.
File No. Civ. 4-80-469
CD-RAP Section 11.5.3**

Gentlemen:

In accordance with Section 11.5.3 of the Consent Decree-Remedial Action Plan in the above captioned matter, please find the enclosed Construction Report for Louisiana Avenue Traffic Improvements on the southern edge of the Reilly Site. This report is issued by the City of St. Louis Park who completed this traffic improvement project.

The Construction Report describes the construction and the procedures for managing soils encountered during construction that may have contained PAH. This report is consistent with the soil management and documentation procedures used for the recent park improvements at the Reilly Site and the Block 7 Construction reconstruction. One difference is that all soil was disposed off site, because there was no space available within the project boundaries to place excavated soil that contains low levels of PAH.

If you have any questions, or require further information, please contact this office.

Sincerely,

William M. Gregg
Project Leader for the
City of St. Louis Park

Enclosure

cc: Jim Olson, City of St. Louis Park